



Bounsun Plastic Ltd is a specialist manufacturer of PVC folding door ,it was located in TianTai ZheJiang China. After 15 years development ,we have become the biggest manufacturer of PVC folding door in China , and now our monthly capacity is about 38*40” HQ .We have always been focused on producing products that exceed the expectations of our customers, both in terms of quality and value for money. The quality of product is paramount to us and a guiding principle for everyone employed within the business. Once you choose BOUNSUN Ltd as your preferred supplier, our company gives you consistently high quality products at the most competitive prices.

Basic info

Location	Tiantai .Zhejiang	Product Break Down %	pvc folding door			
Website	www.pvc-door.cn		100%			
Annual Turnover (2025)	15,700,000USD	Market Break Down%	South America	Europen	Asia	else
Major Products	PVC folding door		35%	30%	20%	15%
Manpower	150	Key Customer	Home Depot ,OBI ,Bauhaus ,Argos ,Kingfish ,Globus , Walmart			
Max Capacity/Month	38x40'HQ/month					

Key Customer :



Company Background for Filament Facility

- Date of Incorporation: Mar. 2010
- Public/Private: Private
- Total Area: 48,000 M2
- No. of Employees: 150
- Average Working Age: 11 Years
- Major Products: PVC folding door
- Brand: Bounsun ®
- Capacity: 3000pcs/day
- Major Market: Europe, South America, USA etc.



Factory Overview




Factory Overview



Factory Overview



Development history



Year	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025
Turnover	\$2,500,000	\$3,200,000	\$4,500,000	\$5,500,000	\$6,000,000	\$6,500,000	\$7,000,000	\$7,500,000	\$8,000,000	\$9,000,000	\$12,000,000	\$13,000,000	\$13,500,000	\$14,200,000	\$15,700,000

Quality Management and Certificate

- CE CERTIFICATE
- REACH CERTIFICATE by INTERTEK
- FUNCTIONAL TESTING REPORT by INTERTEK
- BSCI & SMETA audit by INTERTEK



Intertek	
TEST REPORT PVC FOLDING DOOR	
Report Reference No.	AUT1054039-1
Tested by (name and signature)	Harrison Li
Approved by (name and signature)	Fred Bao
Date of issue	October 14, 2011
Contents	Total test report: 7 pages including: Report text: 4 pages; Appendix A for product photos: 1 page; Appendix B for product installation drawings: 1 page; Revision Summary: 1 page
Testing Laboratory name	Intertek Testing Services Building Products JiaQiao Branch
Address	Building: T32-6, No. 1201 Gul Qiao Road, JiaQiao Development Area, Puzhou District, Shanghai, China, 201206
Testing location	Same as above
Applicant's name	Zhejiang Bousun Plastic Co., Ltd.
Address	No. 699-10 JiGong Road, Taizhou, Zhejiang, China
Test specification:	Standard: --- Non-standard test method: Protocol No. PRACTICE-004, Issue date: June 21, 2011
Test item description	PVC FOLDING DOOR
Trade Mark	BOUSUN
Model and/or type reference	ACC LAM VER GLA
Manufacturer	Zhejiang Bousun Plastic Co., Ltd.
Rating(s)	---
Buyer	Praktiker
Summary of testing: The submitted samples were tested in accordance with specified standards, and tested the result accordingly, refer to test for detail.	
Intertek Testing Services Ltd., Shanghai JiaQiao Branch Building: T32-6, No. 1201 Gul Qiao Road, JiaQiao Development Area, Puzhou District, Shanghai, China Tel: 86-21-6101-1660 Fax: 86-21-6101-1670 Report Sample Revision Date: 2 Feb. 2009	

SMETA.

SMETA Corrective Action Plan Report (CAPR)

Version 6.0



Production Process

mixed material



pelletize



extrusion



packing



loading



printing



shrink film



assembling



cutting



Quality Control - inspection



Falling ball test



Color adjustment



UV test



Salt Spray test

Strength test for Roller



each roller can
withstand 40KG tension


Open and Close test

2.10	Cycle test The test shall be conducted in according with BS EN 1527. The door shall be Installed as the provided instruction, the actuator shall be set on the handle; the cycle speed shall be five cycle per minutes. After cycle test, repeat initial friction test and smooth test, the result shall be compliance.	After opening and closing for 25000 cycles, the test sample door did not have any visible damage, failure, or detachment. The operation of the moving parts was done without any difficulties.	P
------	--	---	---




Accessories

Connection & Roller :



Handle & lock :



Packaging

Inner box



Outer carton



Shrink film & Foam



Finished Products area



